






A1, X1, Y1 B2



Model	A1	A2	X1	X2	Y1	Y2	B1	B2	C1	C2	D	H
PDD 80Lx80R	800	800	772-787	772-787	767-782	767-782	450	450	188-203	188-203	840	2000
PDD 80Lx90R	800	900	772-787	872-887	767-782	867-882	450	450	188-203	288-303	840	2000
PDD 80Lx100R	800	1000	772-787	972-987	767-782	967-982	450	450	188-203	388-403	840	2000
PDD 90Lx80R	900	800	872-887	772-787	867-882	767-782	450	450	288-303	188-203	840	2000
PDD 90Lx90R	900	900	872-887	872-887	867-882	867-882	450	450	288-303	288-303	840	2000
PDD 90Lx100R	900	1000	872-887	972-987	867-882	967-982	450	450	288-303	388-403	840	2000
PDD 100Lx80R	1000	800	972-987	772-787	967-982	767-782	450	450	388-403	188-203	840	2000
PDD 100Lx90R	1000	900	972-987	872-887	967-982	867-882	450	450	388-403	288-303	840	2000
PDD 100Lx100R	1000	1000	972-987	972-987	967-982	967-982	450	450	388-403	388-403	840	2000